



10/12/2011

Show Returns/Repackaged - Product has no visible damage, possibly not in original carton

| Category | Model | Serial | Description | SALE |
|--------------------|---------|-----------|-------------------------------|---------|
| 24" Refrig/Freezer | HC-1011 | 256913703 | 24" INTEGRATED REFRIG/FREEZER | \$2,050 |

Used/ Factory Refurb - Unit has been repaired to work properly, may have been previously used

| Category | Model | Serial | Description | SALE |
|--------------------|---------|-----------|---------------------------|---------|
| 24" Refrig/Freezer | HC-1060 | 253882163 | VERY SMALL DENT LEFT SIDE | \$1,917 |

B Goods - "Scratch n Dent" product (see detailed description for each)

| Description | Model | Serial | Condition | SALE |
|---|----------|------------------------|--|---------|
| 24" Biofresh/Freezer | BFI-1051 | 252123465 | DENTS LEFT SIDE | \$2,450 |
| 30" Refrig/Freezer | CI-1601 | 814373840 | DENTED TOP DOOR (PANEL WILL COVER) | \$3,517 |
| 24" Refrig/Freezer | CS-1310 | 280115661 | LARGE DENT ON RIGHT SIDE | \$2,117 |
| 36" Refrig/Freezer | CS-2060 | 813859949 | 2 SMALL DENTS ON LEFT SIDE NEAR EDGE | \$4,050 |
| 24" Freezer | F-1051 | 279091303 | SMALL DENT REAR RIGHT EDGE | \$2,650 |
| 24" Freezer | F-1051 | 281297625 | TINY DENT ON LEFT REAR EDGE | \$2,650 |
| 24" Refrig/Freezer | HC-1001 | 282767752 | MINOR DENT RIGHT SIDE REAR | \$1,583 |
| 36" Refrig/Freezer | HC-2062 | 804389424 | DENT ON LEFT REAR TOP CORNER | \$4,717 |
| Mini Wine Cabinet | WS-1200 | 810372359 | VERY MINOR SCRATCHES ON TOP | \$1,117 |
| Humidor | XS-200 | 809447822 | DENTS ON BACK & LEFT SIDE | \$1,783 |
| 48" Refrig/Frzr/ Biofresh, Custom Panel | SBS19H0 | 279027340 273932893 | HRB-1110 SIDES DENTED, DOOR MINOR DINGS HF-851 DENTED ON RIGHT FRONT SIDE | \$4,450 |
| 48" Refrig/Freezer, Custom Panel | SBS20H0 | 276828711 255807379 | HC-1001 MINOR LINER DAMAGE, DOOR DING HC-1050 MINOR DENTS ON BOTTOM DOOR | \$3,383 |
| 48" Refrig/Frzr/ Bio/Wine, SS | SBS245* | 248770208 255908373 | RB-1400 SMALL DENT LEFT SIDE BOTTOM WF-1051 GOOD CONDITION, NO DAMAGE | \$6,050 |

***The pricing for this SBS unit includes the SBS kit and top & bottom vent grills - NO ADDITIONAL COST!!**